


XV Tuner Bad Flashed custom file fix


Sometimes when flashing custom files, they might have been corrupted by editing software. This leads to uncontrolled XVTuner crashed and behaviour.

Here are some screenshots of “bad file behaviour”


Here Bike Info data is loaded correctly, even offsets/TPS settings are loaded but the status still says “Connecting to ECU”




Here on Tune Constants Tab we get no data, pressing buttons does nothing or throws error. Connection Status still says “Connecting To ECU”



To fix this please upload a known good map (best use stock maps, here im using latest Dual Mapping for Full Power)



After flashing a good file, this is how a normal behaviour should look like



Video of uploading a good file to bad ECU.

<https://www.youtube.com/watch?v=Sx2lw4u8Fqo>

Video of correct operating XVTuner software.

First 16 seconds are with Ignition turned off, then ignition is turned on and connection is established.

https://youtu.be/IhlpqH3_3AU